





DON'T NEED ANYMORE









Sheet: /Breakouts/
File: breakouts.kicad_sch


Title:


Size: A4
KiCad E.D.A. 8.99.0-2629-g91569cf3cf

Date:


Rev:

Id: 4/10






Sheet: /Servos/ File: Servos.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 8.99.0-2629-g91569cf3cf		Id: 6/10



Sheet: /PWM/ File: PWM.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 8.99.0-2629-g91569cf3cf		Id: 7/10

Lasers:
DONE????

also the laser should be operable via gpio, probably needs a small mosfet or something for it
also undervolting the laser was discussed, may require a lower voltage ldo for that



Sheet: /Lasors/ File: lasor.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. 8.99.0-2629-g91569cf3cf		Id: 8/10

